



S-3XL LAB COAT SIZE CHART




Finished product size table (unit: cm)							
	S	M	L	XL	2XL	3XL	Tolerance
A	112	114	114	115	118	118	±1cm
B	58	63	66	70	75	80	±1cm
C	79	83	87	89	90	91	±1cm
D	30	30	30	32	32	32	±1cm
E	18	20	21.5	23	24	26	±1cm
F	15.5	15.5	15.5	15.5	15.5	15.5	±0.5cm


4XL LAB COAT SIZE CHART



Finished product size table (unit: cm)		
	4XL	Tolerance
A	118	±1cm
B	84	±1cm
C	101	±1cm
D	32	±1cm
E	30	±1cm
F	15.5	±0.5cm



S-4XL LAB JACKET SIZE CHART



Finished product size table (unit: cm)								
	S	M	L	XL	2XL	3XL	4XL	Tolerance
A	78	79	79	80	85	86	87	±1cm
B	63	65	70	73	75	78	85	±1cm
C	85	87	90	92	93	93	97	±1cm
D	30	30	30	31.5	31.5	31.5	31.5	±1cm
E	19	20	21.5	22.5	23.5	25	28.5	±1cm
F	12.5	12.5	12.5	12.5	12.5	12.5	12.5	±0.5cm